

Part Change Notification Number:
 TGEANA_PCN_0022

sales@tglobaltechnology.com
 t: +44 (0)1455 553 510

Date: 22nd September 2020

Parts Affected:

Manufacturer P/N	Digi-Key P/N
DC0004/01 (H48-6S 0.23MM)	DC0004/01(H48-6S0.23MM)-ND
H48-2-100-100-0.5-1A	H48-2-100-100-0.5-1A-ND
H48-2-300-300-0.5-1A	H48-2-300-300-0.5-1A-ND
H48-6-100-100-0.5-1A	H48-6-100-100-0.5-1A-ND
H48-6-300-300-0.5-1A	H48-6-300-300-0.5-1A-ND
H48-6A-100-100-0.5-1A	H48-6A-100-100-0.5-1A-ND
H48-6A-300-300-0.5-1A	H48-6A-300-300-0.5-1A-ND
H48-6A-320-320-0.3-1A	H48-6A-320-320-0.3-1A-ND
H48-6G-100-100-0.5-1A	H48-6G-100-100-0.5-1A-ND
H48-6G-200-200-0.3-1A	H48-6G-200-200-0.3-1A-ND
H48-6G-300-300-0.5-1A	H48-6G-300-300-0.5-1A-ND
H48-6G-320-320-0.8-0-1A	H48-6G-320-320-0.8-0-1A-ND
H48-6G-48.2-82-1.5-1A	H48-6G-48.2-82-1.5-1A-ND
H48-6G-55.4-33.8-5-1A	H48-6G-55.4-33.8-5-1A-ND
H48-6G-57.15-47.75-2-1A	H48-6G-57.15-47.75-2-1A-ND
H48-6G-58.6-61.6-03-1A	H48-6G-58.6-61.6-03-1A-ND
H48-6S-100-100-0.23-0	H48-6S-100-100-0.23-0-ND
H48-6S-300-300-0.23-0	H48-6S-300-300-0.23-0-ND
L37-3-10.8-10.8-1.5-1A	L37-3-10.8-10.8-1.5-1A-ND
L37-3-101.10-11.64-0.25-DWG	L37-3-101.10-11.64-0.25-DWG-ND
L37-3-12.6-10.1-1.5-1A	L37-3-12.6-10.1-1.5-1A-ND
L37-3-150-150-0.5-1A	L37-3-150-150-0.5-1A-ND
L37-3-189.99-12.19-0.25DWG	L37-3-189.99-12.19-0.25DWG-ND
L37-3-21.3-19.4-1.5-1A	L37-3-21.3-19.4-1.5-1A-ND
L37-3-300-300-0.5-1A	L37-3-300-300-0.5-1A-ND
L37-3-348.74-12.19-0.25-DWG	L37-3-348.74-12.19-0.25-DWG-ND
L37-3-8.3-9.6-1.5-1A	L37-3-8.3-9.6-1.5-1A-ND
L37-3-91.25-88.5-2-1A	L37-3-91.25-88.5-2-1A-ND
L37-3-DIA50.8-0.25-DWG	L37-3-DIA50.8-0.25-DWG-ND
L37-3F-100-100-0.25-0	L37-3F-100-100-0.25-0-ND
L37-3F-100-100-0.25-1A	L37-3F-100-100-0.25-1A-ND
L37-3F-100-100-0.3-1A	L37-3F-100-100-0.3-1A-ND
L37-3F-100-100-0.45-0	L37-3F-100-100-0.45-0-ND
L37-3F-100-100-0.45-1A	L37-3F-100-100-0.45-1A-ND
L373F-101.09-11.55-0.25-DWG	1168-L373F-101.09-11.55-0.25-DWG-ND
L37-3F-105-27-0.25-1A	L37-3F-105-27-0.25-1A-ND
L37-3F-15.1-11.5-0.3-1A	L37-3F-15.1-11.5-0.3-1A-ND

L37-3F-300-300-0.25-0	L37-3F-300-300-0.25-0-ND
L37-3F-300-300-0.25-1A	L37-3F-300-300-0.25-1A-ND
L37-3F-300-300-0.3-1A	L37-3F-300-300-0.3-1A-ND
L37-3F-300-300-0.45-0	L37-3F-300-300-0.45-0-ND
L37-3F-300-300-0.45-1A	L37-3F-300-300-0.45-1A-ND
L373F-348.74-12.19-0.25-DWG	1168-L373F-348.74-12.19-0.25-DWG-ND
L37-3F-46-44.5-0.25-1A	L37-3F-46-44.5-0.25-1A-ND
L37-3L-100-100-0.5-1A	L37-3L-100-100-0.5-1A-ND
L37-3L-300-300-0.5-1A	L37-3L-300-300-0.5-1A-ND
L37-3S-100-100-0.5-1A	L37-3S-100-100-0.5-1A-ND
L37-3S-300-300-0.5-1A	L37-3S-300-300-0.5-1A-ND
L37-5-100-100-0.5-1A	L37-5-100-100-0.5-1A-ND
L37-5-300-300-0.5-1A	L37-5-300-300-0.5-1A-ND
L37-5-320-320-1.5-1A	L37-5-320-320-1.5-1A-ND
TG2030-22.86-15.24-1.5	TG2030-22.86-15.24-1.5-ND
TG404F-200-200-0.3	TG404F-200-200-0.3-ND
TG6050-33.9-11.3-1.0-DWG	TG6050-33.9-11.3-1.0-DWG-ND
TG-6050-8.5-8.5-0.8 WITH 5MM PT	TG-6050-8.5-8.5-0.8WITH5MMPT-ND
TG-OD-160.2	TG-OD-160.2-ND
TG-OD-93.8	TG-OD-93.8-ND
TGX LED_FRONT_ALL-IN-ONE	TGXLED_FRONT_ALL-IN-ONE-ND
TGX LED_POWERBOARD	TGXLED_POWERBOARD-ND

Reason: System conflict resolved

Description: Due to new part numbering systems that have been implemented by T-Global and Digi-Key Electronics, the parts in the table above could no longer be supplied due to a system conflict. However, T-Global and Digi-Key electronics have resolved this problem and these parts are now available for purchase once more.

Please note that in conjunction with this change, these products are being renamed. Further details of this change may be found here:

<https://www.tglobaltechnology.com/2020/07/17/notification-material-part-numbers-change/>

Should you require more details or wish to discuss this please do not hesitate to contact us at sales@tglobaltechnology.com. We apologise for any inconvenience this may have caused.

Start date: Effective immediately (22nd September 2020)



Approved By: Duncan Bell, General Manager